


McKay Creek

At M-129 (north)
MCK-8



Upstream



Downstream



McKay Creek

At M-129 (north)
MCK-8

McKay Creek at M-129 (north crossing)

Site I.D.: MCK-8
GPS Coordinates: N 46.06764
W 84.36302
Township: Clark
County: Mackinac
Adjacent Landowners: Private

Road Information

Jurisdiction: MDOT
Surface: Paved
Width at Crossing: 48 feet
Maintenance: Year around
Low point: At stream
Drainage Control Features: None
Approach Length: Left: 1 mile
Right: 1 mile
Slope: Left: 0 percent
Right: 0 percent
Ditch/shoulder vegetation: Left: Heavy
Right: Heavy
Average Width of Grade: 80 feet
Runoff Path: Ditch

Stream Characteristics

Average Width: Upstream: Flooded
Downstream: 3 feet
Average Depth: Upstream: Flooded
Downstream: 8 inches
Average Current: Upstream: Slow
Downstream: Moderate
Substrate Type: Upstream: Muck
Downstream: Muck

Adjacent Wetlands:

Yes
Visible Down Cutting: No

Culvert Information

Culvert Type: Single
Length: 67 feet
Diameter: 4 feet
Material: Concrete
Condition: Good
Culvert Flow: Clear
Fish Passage Problem: No
Fill Depth: Inlet: 2 feet
Outlet: 2 feet
Embankment Slopes: Inlet: >2:1
Outlet: >2:1



McKay Creek

At M-129 (north)
MCK-8

Conditions and Treatment

Erosion Conditions

- None

Recommended Treatment

- None

Erosion Severity Rating: Minor (14)

Overall Condition Rating: Minor

Cost: See BMP Cost Tables

Comments: None