


# Pollock Creek

At M-134  
PLK-2



Upstream



Downstream



# Pollock Creek

At M-134  
PLK-2

**Pollock Creek at M-134**

**Site I.D.:** PLK-2  
**GPS Coordinates:** N 46.00576  
W 84.39648  
**Township:** Clark  
**County:** Mackinac  
**Adjacent Landowners:** Private

**Road Information**

**Jurisdiction:** MDOT  
**Surface:** Paved  
**Width at Crossing:** 42 feet  
**Maintenance:** Year around  
**Low point:** At stream  
**Drainage Control Features:** None  
**Approach Length:** Left: 0.4 mile  
Right: 0.125 mile  
**Slope:** Left: 1-5 percent  
Right: 0 percent  
**Ditch/shoulder vegetation:** Left: Heavy  
Right: Heavy  
**Average Width of Grade:** 50 feet  
**Runoff Path:** Ditch

**Stream Characteristics**

**Average Width:** Upstream: 4 feet  
Downstream: 2 feet  
**Average Depth:** Upstream: 6 inches  
Downstream: 6 inches  
**Average Current:** Upstream: Moderate  
Downstream: Moderate  
**Substrate Type:** Upstream: Sand/gravel/muck  
Downstream: Sand/gravel

**Adjacent Wetlands:**

Yes  
**Visible Down Cutting:** No

**Culvert Information**

**Culvert Type:** Single  
**Length:** 54 feet  
**Diameter:** 4 feet  
**Material:** Concrete  
**Condition:** Good  
**Culvert Flow:** Clear  
**Fish Passage Problem:** No  
**Fill Depth:** Inlet: 2 feet  
Outlet: 2 feet  
**Embankment Slopes:** Inlet: >2:1  
Outlet: >2:1



# Pollock Creek

At M-134  
PLK-2

## Conditions and Treatment

### Erosion Conditions

- None

### Recommended Treatment

- None

**Erosion Severity Rating:** Moderate (18)

**Overall Condition Rating:** Minor

**Cost:** See BMP Cost Tables

**Comments:** Riparian vegetation should be maintained along the creek's course on M-134.