


# Pollock Creek

At State Road  
PLK-3



Upstream



Downstream



# Pollock Creek

At State Road  
PLK-3

**Pollock Creek at State Road**

**Site I.D.:** PLK-3  
**GPS Coordinates:** N 46.0061  
W 84.39791  
**Township:** Clark  
**County:** Mackinac  
**Adjacent Landowners:** State/private

**Road Information**

**Jurisdiction:** MCRC  
**Surface:** Gravel  
**Width at Crossing:** 30 feet  
**Maintenance:** Year around  
**Low point:** At stream  
**Drainage Control Features:** None  
**Approach Length:** Left: 56 feet  
Right: 0.2 mile  
**Slope:** Left: 1-5 percent  
Right: 1-5 percent  
**Ditch/shoulder vegetation:** Left: Heavy  
Right: Heavy  
**Average Width of Grade:** 62 feet  
**Runoff Path:** Roadway

**Stream Characteristics**

**Average Width:** Upstream: 2 feet  
Downstream: 4 feet  
**Average Depth:** Upstream: 6 inches  
Downstream: 6 inches  
**Average Current:** Upstream: Moderate  
Downstream: Moderate  
**Substrate Type:** Upstream: Sand/gravel  
Downstream: Sand/grav/cobble

**Adjacent Wetlands:**

**Adjacent Wetlands:** No  
**Visible Down Cutting:** No

**Culvert Information**

**Culvert Type:** Single  
**Length:** 50 feet  
**Diameter:** 4 feet  
**Material:** Concrete  
**Condition:** Good  
**Culvert Flow:** Clear  
**Fish Passage Problem:** No  
**Fill Depth:** Inlet: 4-6 inches  
Outlet: 4-6 inches  
**Embankment Slopes:** Inlet: 2:1  
Outlet: 2:1



# Pollock Creek

At State Road  
PLK-3

## Conditions and Treatment

### Erosion Conditions

- None

### Recommended Treatment

- None

**Erosion Severity Rating:** Moderate (17)

**Overall Condition Rating:** Minor

**Cost:** See BMP Cost Tables

**Comments:** None